ELECTRICITY ORDINANCE (Chapter 406)

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ('the Ordinance'), I was satisfied on evidence and decided that HKP Engineering (Materials) Limited had failed to comply with regulation 4(2) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that HKP Engineering (Materials) Limited, being a registered electrical contractor (Registration No.: 031509), on or about 17 June 2022, failed to provide a residual current device (RCD) for an industrial socket outlet in Room HHB-UG11 at the PolyU Hung Hom Bay Campus, 8 Hung Lok Road, Hung Hom, Kowloon and hence failed to ensure that the fixed electrical installation was designed, constructed, installed and protected so as to prevent danger.

It is further notified that in accordance with section 36(1)(b)(i) of the Ordinance, I have reprimanded HKP Engineering (Materials) Limited.

22 September 2023

CHU Kei-ming, Barry for Director of Electrical and Mechanical Services