

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 22 February 2023 in accordance with regulation 10 of the Regulations, that WONG Chun-yin trading as J Tat License Consultant Company, being a Class 2 registered Fire Service Installation Contractor, had been guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that having been engaged to maintain, inspect, modify or repair the fire service installations at the premises at Tower 18, Hong Kong Parkview, 88 Tai Tam Reservoir Road, Hong Kong between 24 June 2022 and 6 July 2022, in which the fire service installations, namely, Fire Hydrant/Hose Reel System, were expected to be shut down overnight or for more than 24 hours continuously, did fail to submit 'Notification of FSI Shutdown' to the Fire Services Department, such that the contractor is unfit to be on the register of fire service installation contractors.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that the name of WONG Chun-yin trading as J Tat License Consultant Company be removed from the register of fire service installation contractors in Class 2 for a period of THREE WEEKS, which will take effect from 27 March 2023 to 16 April 2023.

HOI Wai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*