

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 12 May 2022 in accordance with regulation 10 of the Regulations, that LEUNG Kam-hing, being a Class 3 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that incorrect date of next maintenance was filled in on the maintenance labels on 18 fire extinguishers at S.K.H. Ho Chak Wan Primary School, Cheung Hang Estate, Tsing Yi, New Territories on 26 November 2020, which contravened the Code of Practice for Inspection, Testing and Maintenance of Installations and Equipment of the Fire Services Department, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that LEUNG Kam-hing be removed from the register of fire service installation contractors in Class 3 for a period of two months, which order will take effect from 14 June 2022 to 13 August 2022.

KEUNG Sai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*