

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 15 December 2021 in accordance with regulation 10 of the Regulations, that Kin Ying Contracting Limited, being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 7 November 2020, during the annual inspection of the Fire Alarm System of Jone Mult Industrial Building, 169 Wai Yip Street, Kwun Tong, Kowloon, only two fire alarm call points on two separate floors of the building were inspected and tested. As the contractor did not inspect the fire alarm call points on other floors of the building, the defective fire alarm call point on 1st Floor of the building had not been discovered, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that Kin Ying Contracting Limited be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of two weeks, which order will take effect from 15 January 2022 to 28 January 2022.

KEUNG Sai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*