

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 15 December 2021 in accordance with regulation 10 of the Regulations, that China Status Development and Engineering Company Limited, being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on or before 25 November 2020, you did fail to notify the Fire Services Department of fire service installation, namely the Sprinkler System, on 28th Floor, Tower 1, Ever Gain Plaza, 88 Container Port Road, Kwai Chung, New Territories would be shut down overnight or for more than 24 hours continuously for inspection, maintenance, modification or repair, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that China Status Development and Engineering Company Limited be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of three weeks, which order will take effect from 15 January 2022 to 4 February 2022.

KEUNG Sai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*