

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 15 December 2021 in accordance with regulation 10 of the Regulations, that HUI Ham-so, being a Class 3 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 6 June 2020, the contractor did conduct an annual inspection to the portable fire extinguisher at the pump room on 2nd Floor, No. 45 Dundas Street, Mong Kok, Kowloon and labelled the inspection result of such fire extinguisher as 'PASS', but indeed the fire extinguisher was slightly deformed, severely rusted and cracked, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that HUI Ham-so be removed from the register of fire service installation contractors in Class 3 for a period of four months, which order will take effect from 15 January 2022 to 14 May 2022.

KEUNG Sai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*