

FIRE SERVICES ORDINANCE (CHAPTER 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 15 December 2021 in accordance with regulation 10 of the Regulations, that Lap Fung Fire Engineering Company Limited, being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 16 September 2019, the contractor did issue a Certificate of Fire Services Installation and Equipment which was false or misleading in a material particular, alleging that the sprinkler system of the whole building of Smiling Shau Kei Wan Plaza, 17 Nam Hong Street, Shau Kei Wan, Hong Kong was annually inspected on 3 September 2019 and conformed to FSD requirement. In fact, the contractor did only inspect the sprinkler system serving the commercial area and carpark of the building, whereas, did not inspect the sprinkler system serving the elderly nursing centre, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that Lap Fung Fire Engineering Company Limited be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of two months, which order will take effect from 15 January 2022 to 14 March 2022.

KEUNG Sai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*