

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 22 September 2022 in accordance with regulation 10 of the Regulations, that Shin Fai Engineering Services Limited, being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 27 July 2021, during the annual inspection of the Sprinkler System at Car Park, Tai Po Garden, 1 Mui Shu Hang Road, Tai Po, N.T., did not test and inspect the cables of the sprinkler pumps and thus failed to ensure that those cables are free from undue deterioration, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that the name of Shin Fai Engineering Services Limited be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of two months, which order will take effect from 25 October 2022 to 24 December 2022.

HOI Wai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*