

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE  
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 14 September 2023 in accordance with regulation 10 of the Regulations, that MOK Siu-wing, being a Class 3 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 28 January 2022 at Tin Yee House, Ting Ping Estate, 48 Ting Ping Road, Sheung Shui, fill in incorrect date of next maintenance on the maintenance labels on 3 fire extinguishers, which contravenes the Codes of Practice for Inspection, Testing and Maintenance of Installations and Equipment of Fire Services Department, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that MOK Siu-wing be removed from the register of fire service installation contractors in Class 3 for a period of SIX WEEKS, which order will take effect from 17 October 2023 to 27 November 2023.

CHAN Man-hon, Steven *Chairman, Registered Fire Service  
Installation Contractors Disciplinary Board*