

第 223 號公告

屋宇署

建築物條例 (第 123 章)

(第 35 條)

命令的送達

本人現按照《建築物條例》第 35 條的但書規定，附上命令副本一份連同收件人的現成資料，詳情如下：

香港建築事務監督

建築物條例

(第 123 章)

建築事務監督根據第 26 條規定頒布的命令

命令編號： D00004/HK/10

日期： 2010年1月15日

檔案編號： EB/3140/63/P01

致： **香港歌頓道2及4號**
之擁有人

本人認為，位於(地址) 香港歌頓道2及4號

即坐落(地段編號) I.L. 2166 s.D R.P.


位於上述建築物公用部分的建築物可變得危險。

2. 本人現行使《建築物條例》第 26 條所賦予的權力，宣布該建築物可變得危險，並命令你進行以下工程。工程須最遲於 **2010年3月15日** 前展開，並於 **2010年5月14日** 完成。有關工程為：

就樓宇公共地方及外部而言：

- (a) 清除建築物的鋼筋混凝土結構中鬆脫、破裂及損毀的混凝土；清理現有外露鋼筋上鬆脫的鐵銹及雜物；如有需要，加裝鋼筋及固定其位置，並將鋼筋混凝土結構修復原狀。在澆注新混凝土前，必須通知建築事務監督，而建築事務監督可能會就這方面進行有關審查。
- (b) 清除內外牆所有鬆脫及損毀的批盪。
- (c) 修補、裝穩或更換所有鬆脫及破損的窗框，以及更換破爛的窗玻璃。

本命令指定進行的所有工程，必須達到建築事務監督接受的標準，並須符合規例。

建築事務監督
(高級屋宇測量師 鄧海坤  代行)

副本送：土地註冊處處長 - 供註冊用
高級文書主任

請留意《建築物條例》第 26(3)、26(3A) 及 33 條的條文。

本命令的正本已於命令發出當日張貼在有關樓宇一顯眼處。

2010 年 1 月 15 日

建築事務監督
(總屋宇測量師莊永康代行)

Ownership List

Order No.: D00004/HK/10

File Ref.: EB/3140/63/P01

Address: Nos. 2 & 4 Gordon Road, Hong Kong

香港歌頓道2及4號

Ground Floor, Yard & Cockloft, 2 & 4 Gordon Road, Hong Kong	LAU LAI PING (劉麗屏) WONG KA KAM (王加錦)
Flat A on 1/F, 2 & 4 Gordon Road, Hong Kong	CHING TSAN PONG (程贊邦)
Flat B on 1/F including Open Roof 2 & 4 Gordon Road, Hong Kong	CHAN YEE (陳二)
Flat A on 2/F, 2 & 4 Gordon Road, Hong Kong	CHEUNG WAI SI (張維詩)
Flat B on 2/F, 2 & 4 Gordon Road, Hong Kong	CHEUNG KAI MAN (張介民) CHEUNG WAI YING (張維英)
Flat A on 3/F, 2 & 4 Gordon Road, Hong Kong	POON TO (潘桃) LUK YIN JAN (陸燕珍)
Flat B on 3/F, 2 & 4 Gordon Road, Hong Kong	CHUNG KAM-YAU (鍾金有) FUNG TA-HE (馮帶喜)
Flat A on 4/F, 2 & 4 Gordon Road, Hong Kong	LAI SHING (黎盛)
Flat B on 4/F, 2 & 4 Gordon Road, Hong Kong	WONG KAI WING (王啓榮) HONG YEE MAN (康綺文)
Flat A on 5/F & Roof, 2 & 4 Gordon Road, Hong Kong	CHU KAY (朱琦) YUEN CHU SUET-HING (袁朱雪卿)
Flat B on 5/F, 2 & 4 Gordon Road, Hong Kong	WONG YUN MING (黃潤明)
Roof B, 2 & 4 Gordon Road, Hong Kong	SIN LUEN FUNG (單鸞鳳)