

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 12 May 2022 in accordance with regulation 10 of the Regulations, that E W Consultant Limited, being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that before the two previous estimated dates of completion, i.e. before 23 August 2019 and before 28 February 2020, the contractor failed to issue fresh 'Notification to FSD on the occasion that building FSI is shut down for work' to the Director of Fire Services in respect of extensions of shutdown of fire service installation for work at the premises at Wing Wong Commercial Building, No. 557-559 Nathan Road, Mong Kok, Kowloon, such that the contractor is unfit to be on the register of fire service installation contractors.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that E W Consultant Limited be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of three weeks, which order will take effect from 14 June 2022 to 4 July 2022.

KEUNG Sai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*