

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 15 December 2021 in accordance with regulation 10 of the Regulations, that Man Leong Fire Services Limited, being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 28 October 2019, the contractor did issue a Certificate of Fire Services Installation and Equipment which was false or misleading in a material particular, alleging that the Sprinkler System of Che Wah Industrial Building, 1-7 Kin Hong Street, Kwai Chung, New Territories was inspected on 28 October 2019 and conformed to FSD requirement. In fact, the contractor did not properly calibrate the cut-in pressure of the sprinkler pump of the Sprinkler System concerned, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that Man Leong Fire Services Limited be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of two months, which order will take effect from 15 January 2022 to 14 March 2022.

KEUNG Sai-ming *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*