

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 13 September 2023 in accordance with regulation 10 of the Regulations, that F.S. Engineering Company Limited, being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that from 16 April 2022 to 25 April 2022, during the annual inspection of the Fire Hydrant/Hose Reel System at Yun Fung House, Block D, Ning Fung Court, Kwai Chung, N.T., was failed to observe the intermediate pump running for at least 10 minutes, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that F.S. Engineering Company Limited be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of THREE MONTHS, which order will take effect from 16 October 2023 to 15 January 2024 .

CHAN Man-hon, Steven *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*