FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 14 September 2023 in accordance with regulation 10 of the Regulations, that Wenden Engineering Service Co., Ltd., being a Class 1 and Class 2 registered Fire Service Installation Contractor, on 8 December 2022, was convicted by the Eastern Magistrates' Courts (Case No. ESS 28061/2022) of contravening regulation 9(3)(b) of the Fire Service (Installations and Equipment) Regulations, made under the Fire Services Ordinance, Chapter 95, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

The details were that Wenden Engineering Service Company Limited carried out repair works on the fire alarm system of Lee Shau Kee Building, The Chinese University of Hong Kong and issued a certificate of fire service installation and equipment on 21 April 2022 which revealed that the 4 batteries of the fire alarm system were replaced, but in fact, the 4 batteries of the system were not replaced.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that Wenden Engineering Service Co., Ltd. be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of TWO MONTHS, which order will take effect from 17 October 2023 to 16 December 2023.

CHAN Man-hon, Steven Chairman, Registered Fire Service Installation Contractors Disciplinary Board