

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 14 September 2023 in accordance with regulation 10 of the Regulations, that LAM Kai-ming and WONG Pak-cheong trading as Man On Fire Engineering Co., being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 19 November 2022 at Block B, Hung Kwong Building, 2A-2P Tung Choi Street, Mongkok, the contractor failed to notify the Fire Services Department the defect(s) as soon as possible within 24 hours after the defect(s) is/are identified when having been employed to repair the fire alarm system and fire hydrant/hose reel system of which the work(s) is/are expected to be carried out overnight or for more than 24 hours continuously, such that the contractor is unfit to be on the register of fire service installation contractors.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that LAM Kai-ming and WONG Pak-cheong trading as Man On Fire Engineering Co. be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of THREE WEEKS, which order will take effect from 17 October 2023 to 6 November 2023.

CHAN Man-hon, Steven *Chairman, Registered Fire Service
Installation Contractors Disciplinary Board*