

FIRE SERVICES ORDINANCE (Chapter 95)

ORDER MADE BY THE REGISTERED FIRE SERVICE  
INSTALLATION CONTRACTORS DISCIPLINARY BOARD

It is hereby notified that a Disciplinary Board appointed by the Chief Executive under regulation 9 of the Fire Service (Installation Contractors) Regulations (the 'Regulations'), subsidiary legislation of the Fire Services Ordinance, Chapter 95, Laws of Hong Kong, was satisfied after a due inquiry held on 14 September 2023 in accordance with regulation 10 of the Regulations, that Yiu Wah (Kogarah) Co. Ltd., being a Class 1 and Class 2 registered Fire Service Installation Contractor, was guilty of improper conduct or negligence in the installation, maintenance, repair or inspection of fire service installation or equipment, in that on 31 January 2022, issued a Certificate of Fire Service Installation and Equipment which was false or misleading in a material particular, stating that, including but not limited to, the sprinkler system of Overseas Trust Bank Building, No. 160 Gloucester Road, Wan Chai, Hong Kong was annually inspected. However, particulars about non-compliance of the sprinkler system with the Fire Services Department requirements were not set out in the certificate and the annual inspection was not properly completed, such that its continued inclusion in the register of fire service installation contractors will be prejudicial to the due administration of the Fire Services Ordinance.

It is further notified that pursuant to regulation 10(2)(a) of the Regulations, the said Disciplinary Board ordered that Yiu Wah (Kogarah) Co. Ltd. be removed from the register of fire service installation contractors in Class 1 and Class 2 for a period of TWO MONTHS, which order will take effect from 17 October 2023 to 16 December 2023.

CHAN Man-hon, Steven *Chairman, Registered Fire Service  
Installation Contractors Disciplinary Board*