

BUILDINGS ORDINANCE (Chapter 123)  
(Section 35)

SERVICE OF ORDER

In accordance with the proviso to section 35 of the Buildings Ordinance, I append a copy of an order together with the available particulars of the persons to whom they are addressed as detailed below:—

**BUILDINGS ORDINANCE  
(CHAPTER 123)**

**Order by the Building Authority under section 27A**

Order No. DH0014/NT/22/C

BD Reference No.: BD DH 25/12/NT

To: Owners of Cheung Chau Lot No.966


Date : 18 February, 2022

I am of the opinion that the natural, formed or man-made land and the earth-retaining structure (Sub-division 2 of Feature 14NW-D/CR179 as shown coloured red on the attached plan) on Cheung Chau Lot No. 966 are liable to become so dangerous that they will collapse or be likely to collapse, either totally or partially, and thereby cause or be likely to cause a risk of injury to persons or damage to property.

2. In exercise of the powers vested in me under section 27A of the Buildings Ordinance, I hereby declare that such natural, formed or man-made land and earth retaining structure are liable to become dangerous and I HEREBY ORDER you as the owner of the land and structure, to carry out the following work :-

- a) appoint an authorized person and a registered geotechnical engineer within 2 months of the date of this Order to undertake the investigation required below; and
- b) investigate, analyse, and report on the above natural, formed or man-made land and the earth-retaining structure, and submit remedial/preventive work proposals for approval by the Building Authority based on the findings of the investigation within 7 months of the date of this Order.

3. All work as stipulated above in this Order shall be carried out to such standard acceptable to the Building Authority and in compliance with regulations.

  
(YAN) Tik-pang  
Senior Building Surveyor/ Slope Safety  
for Building Authority


Note

Subject to the findings of the investigation work as stipulated in this Order, you shall carry out any remedial/preventive work as required or approved by the Building Authority. Your attention is drawn to section 27A(2B) of the Buildings Ordinance that the Building Authority may by order in writing require the carrying out of such remedial/preventive work as appropriate within the specified time to make the land and structure safe. Under section 27A(2C), all work shall be carried out to such standard acceptable to the Building Authority and in compliance with regulations. Please also note that under section 27A(3) and (3A) of the Buildings Ordinance, the Building Authority may in certain circumstances carry out or cause to be carried out the work or investigation specified in the Order in which the cost thereof shall be recoverable from you or your successor in title as appropriate.

The original copy of this order was posted upon a conspicuous part of the identified premises on its date of issue.

18 February 2022

CHIK Kin-hang *Chief Building Surveyor/SS*  
for Building Authority



As shown coloured red  
 圖示紅色部分  
 Sub-division No. 2 of Feature No. 14NW-D/CR179 as  
 referred to in Order No. DH0014/NT/22/C  
 關於命令DH0014/NT/22/C號  
 地物編號: 14NW-D/CR179 的分割部分2

Legend/圖例

- - - - - LOT BOUNDARY 地段界線
- EXTENT OF DH ORDER 危險斜坡修葺令範圍
- "R" COLOURED RED 紅色部分

**Location Plan**  
**位置圖**

Lot No./地段編號:  Cheung Chau Lot No. 966	BD Reference No.: 檔案編號:	BD DH 25/12/NT
	This plan is for indication purpose only 此圖只作指示用途	