

G.N. 1931

ELECTRICITY ORDINANCE (Chapter 406)

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ('the Ordinance'), I was satisfied on evidence and decided that Wah Fung Electric Engineering Company Limited had failed to comply with the Regulation 13(1) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that Wah Fung Electric Engineering Company Limited, being a registered electrical contractor (Registration No.: 022953), between January and July 2015, at Dragons Range, 33 Lai Ping Road, Kau To Shan, Sha Tin, New Territories, failed to provide electrical cable of sufficient conductor cross-sectional area (4 mm²) for the electrical circuit protection device with rating 32A in order to comply with the relevant Code of Practice for the Electricity (Wiring) Regulations.

It is further notified that in accordance with section 36(1)(b)(i) of the Ordinance, I have reprimanded Wah Fung Electric Engineering Company Limited.

22 April 2022

CHU Kei-ming for *Director of Electrical and Mechanical Services*