

G.N. 814

ELECTRICITY ORDINANCE (Chapter 406)

It is hereby notified that in accordance with section 37 of the Electricity Ordinance (Chapter 406) ('the Ordinance'), I was satisfied on evidence and decided that Ming Tang Water-electric Air-condition Engineering Co had failed to comply with regulation 14(1) of the Electricity (Wiring) Regulations made under section 59 of the Ordinance in that Ming Tang Water-electric Air-condition Engineering Co, being a registered electrical contractor (Registration No.: 002038), on or about 30 December 2020, failed to properly design the enclosure of a wiring installation at the Hong Kong Playground Association Jockey Club Tsing Yi Integrated Service Centre For Children & Youth so as to prevent danger.

It is further notified that in accordance with section 36(1)(b)(i) of the Ordinance, I have reprimanded Ming Tang Water-electric Air-condition Engineering Co.

3 February 2023

CHU Kei-ming for *Director of Electrical and Mechanical Services*